

Schruppfräser (VHW) Z = 3

Rechts- oder Linkslauf; Li./pos. 10% Aufpreis; Li./neg. auf Anfrage ; ØD = ØS



Roughing Cutter (Solid-TC) Z = 3

R/H or L/H cutting; Li.-pos. 10% surcharge; Li.-neg. on request; ØD = ØS

Ø D (mm)	L1 (mm)	L (mm)	Art. Nr. xx	E / Stück		E / piece
				1 - 4	> 5	> 15
8	22	70	144.08.22.xx	83,20	79,40	75,70
8	32	80	144.08.32.xx	90,20	86,10	82,10
8	42	90	144.08.42.xx	96,40	92,10	87,80
10	32	80	144.10.32.xx	96,40	92,10	87,80
10	42	90	144.10.42.xx	117,40	112,10	111,50
10	52	100	144.10.52.xx	122,50	117,00	111,50
12	32	80	144.12.32.xx	124,40	118,80	113,20
12	42	90	144.12.42.xx	136,50	130,40	124,20
12	52	100	144.12.52.xx	153,10	146,20	139,30
14	32	80	144.14.32.xx	156,30	149,30	142,20
14	42	90	144.14.42.xx	172,60	164,80	157,00
14	52	100	144.14.52.xx	185,10	176,80	168,50
16	42	90	144.16.42.xx	191,30	182,60	174,10
16	52	100	144.16.52.xx	197,90	189,00	180,00
16	72	120	144.16.72.xx	233,70	223,20	212,70
18	52	100	144.18.52.xx	236,00	225,40	214,70
18	72	120	144.18.72.xx	282,30	269,60	256,90
18	102	150	144.18.102.xx	352,60	336,70	320,90
20	52	100	144.20.52.xx	252,30	240,90	229,60
20	72	120	144.20.72.xx	336,70	321,60	306,40
20	102	150	144.20.102.xx	390,30	372,70	355,20



Bitte ergänzen Sie die Art.Nr. mit dem xx-Code für die gewünschte Dreh- und Drallrichtung.

Please complete art.no. with the xx-code for sense of rotation and axial angel.

Beispiel / Example : 144.16.72.11 = links / positiv

left / positive

11 **12**
links / left
positiv negativ

01 **02**
rechts / right
positiv negativ

